

KING COU / INTERNATIONAL AIRPORT INC NT REPORT

INCIDENT:

DATE OCCURRED 2-April-93

DATE REPORTED ✓

Fuel Spill

TIME OCCURRED 1648

TIME REPORTED

LOCATION(S) OF OCCURRENCE:

Southeast Aircraft Parking

REPORTED BY:

PHONE NO(S):

Flightcraft

SUMMARY:

A Flightcraft employee, Rob Dinklecamp, observed a parked Cessna 182, N164P, leaking fuel. Flightcraft used their pads and had most of the fuel cleaned up prior to our arrival. FD#2 with Officer Dickie used cejer and 100 gallons of water to clean the area. The aircraft owner, Jackie Kerzer, came to the scene and was able to stop the leak - a defect in the fueling system will be repaired.

OFFICERS:

ACTION:

LEB	<u>CLD</u>	GO	<u>GO</u>	JW	<u>JW</u>
JEB	<u>JE</u>	LGR	<u>LGR</u>	FILED	
BLC	<u>TKL</u>	GCS	<u>GCS</u>	BY	
SHD	<u>PEM</u>	JRV	<u>JRV</u>		